



November 2, 2019

IGAU/SECT/11-19/02

To
National Stock Exchange of India Limited
Exchange Plaza, C - 1, Block G
Bandra Kurla Complex
Bandra - (E)
Mumbai - 400 051

To
Department of Corporate Services
BSE Limited
Phiroze Jeejeebhoy Towers
Dalal Street
Mumbai - 400 001

Symbol: INDIGO

Scrip Code: 539448

Dear Sir,

Sub : Disclosure under Regulation 30 of the SEBI (Listing Obligations and Disclosure Requirements) Regulations, 2015 – news clarification

We refer to your email dated November 1, 2019 in which the Company has been requested to submit clarification to the media report - "IndiGo plane turns back after engine stalls mid-air, 4th incident in a week".

In this context, we wish to submit that the article is factually correct. The Company has initiated a engine change program in accordance with the directive given by Directorate General of Civil Aviation ("DGCA").

The Company has already informed the stock exchanges about a new DGCA directive, which replaces the old directive referred to in the Press article. A filing on the new DGCA directive has already been made to the stock exchanges on November 1, 2019.

The Company is compliant with all global and more stringent DGCA guidelines.

We trust this clarifies the media report.



Please let us know if you require any further information or clarifications from us.

For InterGlobe Aviation Limited

A handwritten signature in blue ink, appearing to be "Sanjay Gupta", written over a circular blue stamp.

Sanjay Gupta



Company Secretary and Chief Compliance Officer